

GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	May 15, 2020		Prepared By: Brad Walls	
	Temp (Celsius)	Wind Direction	Wind Speed (Km/Hr)	General Conditions
Meteorological Conditions	14-17 ^o C	NW	26	Sunny & Windy
	Removed (pH 2-14)	Processed (pH<2)	Lime	Incoming Wood Chips
Legacy Volume (Mt)	0 Mt	0	169.65 Mt	0 Mt
Composite pH	Pile 33	Pile 34	Pile	Pile
	5.45	5.65		
H²S/ SO² Monitors	No Readings on any monitor (employee and fence lines)			
Site Activities	<ul style="list-style-type: none"> Excavation of legacy material and forming piles 4 loads of lime loaded Debris cleanup on site and fence line Applied Odour suppressant Odour control management monitoring 			
Odour Monitoring	Time – Wind Condition		Odour Detection Level (#/10)	
			On Site - Pad	Off-Site Location – Odour Level
	10:00 am	Slight	0	
	10:15 am	Slight	2	
	10:30 am	Slight		Range Road 250/Twp 250 – 0
	10:45 am	Slight		Range Road 252/Twp 250 – 0
	11:00 am	Slight		Range Road 245/Twp 250 - 0
	11:15 am	Slight	0	
	11:30 am	Slight	2	
	11:45 am	No wind		Range Road 250/Twp 250 - 0
	12:00 pm	No wind		Range Road 252/Twp 250 – 0
12:15 pm	No wind		Range Road 245/Twp 250 - 0	

	Time – Wind Condition		Odour Detection Level (#/10)	
			On Site - Pad	Off-Site Location – Odour Level
	Odour Monitoring	12:30 pm	Slight	0
12:45 pm		Slight	3	
1:00 pm		Slight		Range Road 250/Twp 250 - 0
1:15 pm		No wind		Range Road 252/Twp 250 – 0
1:30 pm		No wind		Range Road 245/Twp 250 – 0
1:45 pm		Slight	0	
2:00 pm		Slight	2	
2:15 pm		Slight		Range Road 250/Twp 250 - 0
2:30 pm		No wind		Range Road 252/Twp 250 – 0
2:45 pm		No wind		Range Road 245/Twp 250 - 0
3:00 pm		Slight	1	
3:15 pm		Slight	3	
3:30 pm		Slight		Range Road 250/Twp 250 - 0
3:45 pm		Slight		Range Road 252/Twp 250 – 0
4:00 pm		Slight		Range Road 245/Twp 250 – 0
4:15 pm		Slight	0	
4:30 pm		Slight	2	