GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	May 22, 2020		**Prepared By**: Brad Walls	
	Temp (Celsius)	**Wind Direction**	**Wind Speed (Km/Hr)**	**General Conditions**
Meteorological Conditions	4-8^0 C	NW	19	Rain

	Removed (pH 2-14)	**Processed (pH<2)**	**Lime**	**Incoming Wood Chips**
Legacy Volume (Mt)	0 Mt	0	0 Mt	0 Mt

Composite pH	**Pile**	**Pile**	**Pile**	**Pile**

H^2S/ $S0^2$ Monitors	No Readings on any monitor (employee and fence lines)

Site Activities	• Excavation of legacy material and forming piles • No loads of legacy or lime were removed • Applied Odour suppressant • Legacy pile and Leachate Pond Odour control • Site operations were ceased due to weather

Odour Monitoring	**Time – Wind Condition**		**Odour Detection Level (#/10)**	
			On Site - Pad	**Off-Site Location – Odour Level**