

GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	June 1, 2020		Prepared By: Brad Walls	
	Temp (Celsius)	Wind Direction At Start of Day	Wind Speed (Km/Hr)	General Conditions
Meteorological Conditions	6-19 ⁰ C	N	14	Sunny
	Removed (pH 2-14)	Processed (pH<2)	Lime	Incoming Wood Chips
Legacy Volume (Mt)	55.37 Mt	0	0 Mt	0 Mt
Composite pH	Pile 41	Pile	Pile	Pile
	5.65			
H²S/ SO² Monitors	No Readings on any monitor (employee and fence lines)			
Site Activities	<ul style="list-style-type: none"> • <u>No</u> excavation of legacy material due to wet site conditions • 3 loads of legacy pile loaded • No lime was loaded • Road Repairs • Applied Odour suppressant • Legacy pile and Leachate Pond Odour control 			
Odour Monitoring	Odour Detection Level (#/10)			
	On Site - Pad	Off-Site Location – Odour Level		
	0			

No odour report as no excavation of material or no forming of new piles, no work on the pad due to wet conditions on the site.