## <u>GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT</u>

Date:		June 8, 2020			Prepared By: Brad Walls		
		Te	emp (Celsius)	Wind Direction	Wind Speed (Km/Hr)	General Conditions	
Meteorological Conditions			9-16 <sup>0</sup> C	SW	10	Clear	
			Removed (pH 2-14)	Processed (pH<2)	Lime	Incoming Wood Chips	
Legacy Volume (Mt)			112.56 Mt	0	0 Mt	0 Mt	
Composite pH			Pile 45	Pile 46	Pile	Pile	
			6.30	6.36			
H <sup>2</sup> S/S0 <sup>2</sup> Monitors No Readings on any monitor (employee and fence lines)							
Site Activities		<ul> <li>Excavation of legacy material and forming piles</li> <li>4 loads of legacy pile loaded</li> <li>Applied Odour suppressant</li> <li>Legacy pile and Leachate Pond Odour control</li> <li>Odour control management monitoring</li> </ul>					
Time		- Wind Condition		Odour Detection Level (#/10)			
			na Condition	On Site - Pad	Off-Site Locati	ion – Odour Level	
	10:00 AM		Slight Wind	0			
	10:15 AM		Slight Wind	0			
	10:30 am		Slight Wind		Range Road 252/Twp 250 – 0		
Odour         10:45 a           Monitoring         11:00 a					Range Road 250/Twp 252 – 1 Range Road 250/Twp 245 - 0		
Monitoring	11:15 a		Slight Wind	0	Marige Moau 230/	1 VV P Z-4-3 - U	
	11:30 am		Slight Wind	0			
	11:45 am		Slight Wind	-	Range Road 252/Range Rd - 0		
	12:00 pm		North Wind		Range Road 250/	_	
			North Wind		Range Road 250/Range Rd - 0		
	12:30 pm		North Wind	0			

	Time \A/i	nd Condition	Odour Detection Level (#/10)		
Odour Monitoring	i ime – wi	na Condition	On Site - Pad	Off-Site Location – Odour Level	
	12:45 pm	North Wind	0		
	1:00 pm	North Wind		Range Road 252/Twp 250 – 1	
	1:15 pm	North Wind		Range Road 250/Twp 252 – 0	
	1:30 pm	North Wind		Range Road 250/Twp 245 – 0	
	1:45 pm	North Wind	0		
	2:00 pm	North Wind	1		
	2:15 pm	North Wind		Range Road 252/Twp 250 – 0	
	2:30 pm	North Wind		Range Road 250/Twp 252 - 1	
	2:45 pm	North Wind		Range Road 250/Range Rd 245 - 0	
	3:00 pm	North Wind	0		