<u>GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT</u>

Date:		June 12, 2020		Prepared By : Brad Walls			
		Temp (Celsius)	Wind Direction At Start of Day	•	General Conditions		
Meteorological Conditions		15-25 ⁰ C	S	15	Sunny		
		Removed (pH 2-14)	Processed (pH<2)	Lime	Incoming Wood Chips		
Legacy Volume (Mt)		175.93 Mt	0	30.67 Mt	0 Mt		
Composite pH		Pile 52	Pile 53	Pile	Pile		
		5.79	6.16				
H ² S/ SO ² Monitors		No Readings on any monitor (employee and fence lines)					
Site Activities		 Excavation of legacy material and forming piles 6 loads of legacy pile loaded 1 load of lime loaded Applied Odour suppressant Legacy pile and Leachate Pond Odour control Odour control management monitoring 					
	Time	Wind Condition	Odour Detection Level (#/10)				
Odour Monitoring	rime –	Wind Condition	On Site - Pad	Off-Site Locat	tion – Odour Level		
	9:45 an	n Slight Wind		Range Road 250)/Twp 252 - 2		
	10:00 aı		0				
	10:15 aı		2	D D 1050)/T 250 0		
	10:30 aı			Range Road 252/Twp 250 – 0 Range Road 252/Twp 252 – 0			
	10:45 aı 11:00 aı			Range Road 250			
	11:15 aı		0	Marige Modu 250	7, 1 W P Z T J U		
	11:30 a		2				
	11:45 aı			Range Road 252	2/Twp 250 – 0		
	12:00 pı			Range Road 250	0/Twp 250 – 0		
	12:15 pı	n Light South Wind		Range Road 250)/Twp 245 – 0		

	Time – Wind Condition		Odour Detection Level (#/10)		
Odour Monitoring			On Site - Pad	Off-Site Location – Odour Level	
	12:30 pm	Light South Wind	0		
	12:45 pm	Light South Wind	2		
	1:00 pm	South Wind		Range Road 252/Twp 250 – 0	
	1:15 pm	South Wind		Range Road 250/Twp 252 – 0	
	1:30 pm	South Wind		Range Road 250/Twp 245 – 0	
	1:45 pm	South Wind	0		
	2:00 pm	South Wind	2		
	2:15 pm	South Wind		Range Road 252/Twp 250 – 0	
	2:30 pm	South Wind		Range Road 250/Twp 252 – 0	
	2:45 pm	Slight Wind		Range Road 250/Twp 245 – 0	
	3:00 pm	Slight Wind	2		