

## GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

<b>Date:</b>	June 15, 2020		<b>Prepared By:</b> Brad Walls	
	<b>Temp (Celsius)</b>	<b>Wind Direction At Start of Day</b>	<b>Wind Speed (Km/Hr)</b>	<b>General Conditions</b>
<b>Meteorological Conditions</b>	10-19 <sup>0</sup> C	SSE	14	Overcast
	<b>Removed (pH 2-14)</b>	<b>Processed (pH&lt;2)</b>	<b>Lime</b>	<b>Incoming Wood Chips</b>
<b>Legacy Volume (Mt)</b>	0 Mt	0	0 Mt	0 Mt
<b>Composite pH</b>	<b>Pile</b>	<b>Pile</b>	<b>Pile</b>	<b>Pile</b>
<b>H<sup>2</sup>S/ SO<sup>2</sup> Monitors</b>	No Readings on any monitor (employee and fence lines)			
<b>Site Activities</b>	<ul style="list-style-type: none"> <li>No legacy or lime was removed from the site.</li> <li>No legacy sampling piles were formed</li> <li>No pH sampling was required</li> <li>No excavation of legacy material and forming piles</li> <li>Legacy pile and Leachate Pond Odour control</li> <li>Only site water and rain management operations in effect</li> </ul>			