## **GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT**

Date:		June 17, 2020		Prepared	Prepared By: Brad Walls		
		Temp (Celsius)	Wind Direction At Start of Day	•	General Conditions		
Meteorological Conditions		11-15 <sup>0</sup> C	NW	21	Rain		
		Removed (pH 2-14)	Processed (pH<2)	Lime	Incoming Wood Chips		
Legacy Volume (Mt)		258.71 Mt	0	0 Mt	0 Mt		
Composite pH		Pile 55	Pile 56	Pile 57	Pile		
		6.09	6.19	6.01			
H <sup>2</sup> S/ S0 <sup>2</sup> Monitors		No Readings on any monitor (employee and fence lines)					
Site Activities		<ul> <li>Excavation of legacy material and forming piles</li> <li>8 loads of legacy pile loaded</li> <li>Applied Odour suppressant</li> <li>Legacy pile and Leachate Pond Odour control</li> <li>Odour control management monitoring</li> <li>Repairs and maintenance of roads due to water damage</li> </ul>					
Time -		Mr. I C. Hills	Odour Detection Level (#/10)				
		Wind Condition	On Site - Pad	Off-Site Locat	ion – Odour Level		
	8:45 an	n South East	0				
	8:50 an			Range Road 250			
	9:00 an			Range Road 250			
Odour	9:15 an			Range Road 252			
Monitoring	9:20 an			Range Road 252			
		o					
	9:30 an				2/Twp 252 – 3		
	9:40 an	n South East		Range Road 252	2/Twp 252 – 3 2/Twp 250 – 0		
	9:40 an 9:45 ar	n South East n South East		Range Road 252 Range Road 250	2/Twp 252 – 3 2/Twp 250 – 0 3/Twp 250 – 0		
	9:40 an	n South East n South East m South East		Range Road 252	2/Twp 252 – 3 2/Twp 250 – 0 2/Twp 250 – 0 2/Twp 252 – 0		

	Time – Wind Condition		Odour Detection Level ( #/10)		
			On Site - Pad	Off-Site Location – Odour Level	
	10:30 am	South East		Range Road 250/Twp 250- 0	
	10:40 am	South East		Range Road 250/Twp 245 – 1	
	10:45 am	North East		Range Road 250/Twp 245 – 3	
	10:50 am	North East		Range Road 250/Twp 245 – 4	
	11:00 am	North East		Range Road 250/Twp 250 – 0	
	11:10 am	North East		Range Road 250/Twp 252 – 0	
	11:25 am	North East		Range Road 250/Twp 245 – 0	
	11:30 am	North East		Range Road 250/Twp 245 – 0	
	11:40 am	North East		Range Road 252/Twp 245 – 0	
	11:45 am	North East		Range Road 250/Twp 245 – 4	
	11:50 am	North East		Range Road 250/Twp 250- 0	
	12:00 pm	South East		Range Road 250/Twp 245 – 2	
	12:15 pm	South East		Range Road 250/Twp 250- 0	
Odour Monitoring	12:25 pm	South East		Range Road 252/Twp 245 – 0	
	12:30 pm	South East		Range Road 250/Twp 250 – 0	
	12:35 pm	South East		Range Road 250/Twp 245 – 0	
	12:45 pm	South East	0		
	1:00 pm	North East	1		
	1:10 pm	North East		Range Road 250/Twp 250 – 0	
	1:15 pm	North East		Range Road 250/Twp 245 – 0	
	1:22 pm	North East		Range Road 250/Twp 245 – 3	
	1:30 pm	North East		Range Road 250/Twp 250 – 0	
	1:35 pm	North East		Range Road 250/Twp 245 – 2	
	1:40 pm	North East		Range Road 250/Twp 245 – 3	
	1:45 pm	North East		Range Road 250/Twp 245 – 4	
	1:50 pm	North East		Range Road 250/Twp 245 – 4	
	2:20 pm	North East		Range Road 250/Twp 245 – 6	
	2:26 pm	North East		Range Road 250/Twp 245 – 2	
	2:30 pm	North East		Range Road 250/Twp 245 – 1	
	2:45 pm	North East	1		