

GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	June 24, 2020			Prepared By: Brad Walls			
	Temp (Celsius)	Wind Direction At Start of Day	Wind Speed (Km/Hr)	General Conditions			
Meteorological Conditions	24 C	NE	8-27	Overcast			
	Legacy (pH 2-14)	Unprocessed Organics	Lime	Incoming Wood Chips			
Volume (Mt)	0	456.05	0	0			
Composite pH	Pile 09	Pile 10	Pile 11	Pile 12	Pile 13	Pile 14	Pile 15
	7.05	7.42	7.32	6.56	6.46	6.44	6.35
H²S/ SO² Monitors	No Readings on any monitor (employee and fence lines)						
Site Activities	<ul style="list-style-type: none"> Excavation of legacy material and forming piles Unprocessed organics loaded off the pad Legacy pile removal - complete Applied Odour suppressant Pad repair Odour control management monitoring 						
Odour Monitoring	Time – Wind Condition		Odour Detection Level (#/10)				
			On Site - Pad	Off-Site Location – Odour Level			
	8:25 am	North East		Range Road 250/Twp 245 – 0			
	8:30 am	North East		Range Road 252/Twp 245 – 0			
	8:35 am	North East		Range Road 250/Twp 250 – 0			
	8:40 am	North East		Range Road 250/Twp 250 – 1			
	8:50 am	North East		Range Road 252/Twp 250 – 0			
	8:55 am	North East		Range Road 252/Twp 252 – 0			
	9:00 am	North East		Range Road 250/Twp 252 – 0			
	9:02 am	North East		Range Road 250/Twp 251 – 0			
	9:05 am	North		Range Road 250/Twp 250 - 0			
	9:10 am	North		Range Road 250/Twp 245 – 0			
9:17 am	North		Range Road 250/Twp 250 – 0				
9:24 am	North		Range Road 250/Twp 250 – 0				

	Time – Wind Condition		Odour Detection Level (#/10)	
			On Site - Pad	Off-Site Location – Odour Level
	Odour Monitoring	9:30 am	North East	
9:32 am		North East	3	
9:40 am		North East		Range Road 250/Twp 250 – 0
9:50 am		South East		Range Road 250/Twp 245 – 0
10:10 am		South East	0	Range Road 250/Twp 250 – 0
10:15 am		South East		Range Road 250/Twp 252 – 0
10:25 am		South East		Range Road 250/Twp 252 – 0
10:30 am		South East		Range Road 250/Twp 245 – 0
10:40 am		South East		Range Road 252/Twp 245 – 0
10:50 am		South East		Range Road 250/Twp 250 – 0
11:00 am		South East		Range Road 250/Twp 250 – 0
11:10 am		South East		Range Road 252/Twp 250 – 0
11:15 am		South East		Range Road 252/Twp 252 – 0
11:20 am		South East		Range Road 250/Twp 251 – 0
11:25 am		South East		Range Road 252/Twp 250 – 0
11:30 am		South East		Range Road 250/Twp 250 – 0
11:40 am		South East		Range Road 250/Twp 245 – 0
11:45 am		South East		Range Road 250/Twp 251 – 0
11:55 am		South East		Range Road 252/Twp 252 – 0
12:00 pm		South East		Range Road 252/Twp 250 – 0
12:10 pm		South East	0	
12:28 pm		South East		Range Road 250/Twp 250 – 0
12:35 pm		South East		Range Road 250/Twp 245 – 0
12:40 pm		South East		Range Road 252/Twp 245 – 0
12:47 pm		South East		Range Road 250/Twp 250 – 0
12:58 pm		South East		Range Road 250/Twp 250 – 0
1:05 pm		South East		Range Road 252/Twp 250 – 0
1:15 pm		South East		Range Road 250/Twp 245 – 0
1:26 pm		South East		Range Road 250/Twp 245 – 0
1:35 pm		South East		Range Road 252/Twp 245 – 0
1:40 pm	South East		Range Road 250/Twp 250 – 0	
1:50 pm	South East		Range Road 252/Twp 250 – 0	
2:00 pm	South East		Range Road 250/Twp 250 – 0	
2:10 pm	South East		Range Road 250/Twp 245 – 0	
2:15 pm	South East		Range Road 252/Twp 250 – 0	
2:25 pm	South East		Range Road 250/Twp 250 – 0	
2:30 pm	South East		Range Road 250/Twp 250 – 0	

	Time	Wind Condition	Odour Detection Level (#/10)	
			On Site - Pad	Off-Site Location – Odour Level
Odour Monitoring	2:40 pm	South East		Range Road 252/Twp 250 – 0
	2:45 pm	South East		Range Road 250/Twp 250 – 2
	2:55 pm	South East		Range Road 250/Twp 250 – 0
	3:10 pm	South East		Range Road 252/Twp 250 – 0
	3:21 pm	South East		Range Road 250/Twp 250 – 0
	3:25 pm	South East	0	