GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:			June 25	, 2020		Prepared By: Brad Walls			
		Temp (Celsius)		Wind Direction At Start of Day		Wind Speed (Km/Hr)		General Conditions	
Meteorological Conditions		12-23 C		WSW		8		Sunny	
		Legacy (pH 2-14)		Unprocessed Organics			Lime	Incoming Wood Chips	
Volume (Mt)		0		387.16			0	0	
Composite pH		Pile 16 6.51	Pile 17 6.26	Pile 18 6.95			Pile 20 6.88	Pile 21 7.00	Pile 22 6.88
H ² S/ SO ² IV	No Readings on any monitor (employee and fence lines)								
 Unprocessed organics loaded off the pad Applied Odour suppressant Pad repair On site maintenance Water management Odour control management monitoring 									
Time		- Wind Condition		Odour Detection Level (#/10)					
	Time Willa Collabor			On Site -	Pad	0	Off-Site Location – Odour Leve		our Level

	Time – Wi	nd Condition	Odour Detection Level (#/10)		
Odour	Time vvi	na condition	On Site - Pad	Off-Site Location – Odour Level	
	8:10 am	South East		Range Road 250/Twp 250 – 0	
	8:20 am	South East		Range Road 250/Twp 245 – 0	
	8:25 am	South East		Range Road 252/Twp 245 – 0	
	8:30 am	South East		Range Road 252/Twp 250 – 0	
	8:40 am	South East		Range Road 250/Twp 245 – 0	
Monitoring	8:46 am	South East		Range Road 250/Twp 251 – 0	
	9:00 am	South East		Range Road 250/Twp 250 – 0	
	9:10 am	South East		Range Road 252/Twp 252 – 0	
	9:15 am South East		Range Road 252/Twp 250 - 0		
	9:20 am South East		Range Road 250/Twp 250 – 0		
	9:25 am	South East		Range Road 250/Twp 245 – 0	
	9:30 am	South East		Range Road 250/Twp 245 – 0	

	Time \A/i	nd Condition	Odour Detection Level (#/10)		
	Time – w		On Site - Pad	Off-Site Location – Odour Level	
	9:35 am	South East		Range Road 252/Twp 245 – 0	
	9:40 am	South East		Range Road 252/Twp 245 – 0	
	9:50 am	South East		Range Road 250/Twp 250 – 0	
	10:00 am	South East		Range Road 252/Twp 250 – 0	
	10:12 am	South East	0		
	10:20 am	South East		Range Road 250/Twp 245 – 0	
	10:25 am	South East		Range Road 250/Twp 250 – 0	
	10:50 am	South East		Range Road 252/Twp 250 – 0	
	11:15 am	South East		Range Road 250/Twp 245 – 0	
	11:25 am	South East		Range Road 252/Twp 245 – 0	
	11:35 am	South East		Range Road 252/Twp 250 – 0	
	11:46 am	South East		Range Road 252/Twp 250 – 0	
	11:57 am	South East		Range Road 250/Twp 250 – 0	
	12:10 pm	South East	0		
Odour	12:20 pm	South East		Range Road 250/Twp 245 – 0	
Monitoring	12:55 pm	South East		Range Road 250/Twp 250 – 0	
	1:10 pm	South East		Range Road 250/Twp 245 – 0	
	1:20 pm	South East		Range Road 252/Twp 245 – 0	
	1:30 pm	South East		Range Road 252/Twp 250 – 0	
	1:40 pm	South East		Range Road 250/Twp 250 – 0	
	1:50 pm	South East		Range Road 252/Twp 250 – 0	
	2:15 pm	South East	0		
	2:27 pm	South East		Range Road 250/Twp 245 – 0	
	2:35 pm	South East		Range Road 252/Twp 245 – 0	
	2:52 pm	South East		Range Road 250/Twp 250 – 0	
	3:12 pm	South East		Range Road 250/Twp 245 – 0	
	3:25 pm	South East		Range Road 250/Twp 250 – 0	
	3:35 pm	South East		Range Road 250/Twp 245 – 0	
	3:45 pm	South East		Range Road 252/Twp 245 – 0	
	3:55 pm	South East		Range Road 250/Twp 245 – 0	
	4:00 pm	South East		Range Road 250/Twp 250 – 0	
	4:10 pm	South East	0		