

GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	April 3, 2020		Prepared By: Brad Walls	
	Temp (celsius)	Wind Direction	Wind Speed (Km/Hr)	General Conditions
Meteorological Conditions	-8 ^o C	SE – AM NE - PM	14-23	Overcast Snowing at times
	Removed (ph 2-14)		Processed (pH<2)	
Legacy Volume (Mt)	112.76 Mt		0	
Composite pH	Pile 2	Pile 3	Pile 4	
	4.8	4.7	Building	
H²S/ SO² Monitors	No Readings on any monitor(employee and fence lines)			
Site Activities	<ul style="list-style-type: none"> Pulled down bench North and North East side to pad floor Loaded 5 trucks from piles 2 & 3 Commenced building pile #4 Spraying for odour on continuous basis Shut down @ 3:45 pm and sprayed piles and legacy pile area to manage odour. 			
Odour Monitoring	Time	Odour Detection Level (#/10)		
		On Pad	1 Mile	2 Mile
	10:00	1	0	0
	11:00	1	0	0
	12:00	1	0	0
	1:00	2	0	0
	2:00	2	0	0
	3:00	1	0	0
	4:00	1	0	0

Note: Strong manure and ammonia odour detected off site coming from the feedlot located directly west of the site. Manure spreading taking place on land South and South East of the site.