

## GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

<b>Date:</b>	April 6, 2020	<b>Prepared By:</b> Brad Walls		
	<b>Temp (celsius)</b>	<b>Wind Direction</b>	<b>Wind Speed (Km/Hr)</b>	<b>General Conditions</b>
<b>Meteorological Conditions</b>	0° C	S	14	Sunny and Clear
	<b>Removed (ph 2-14)</b>		<b>Processed (pH&lt;2)</b>	
<b>Legacy Volume (Mt)</b>	146.10 Mt		0	
<b>Composite pH</b>	<b>Pile 3</b>	<b>Pile 4</b>	<b>Pile 5</b>	
	4.7	5.32	Building	
<b>H<sup>2</sup>S/ SO<sup>2</sup> Monitors</b>	No Readings on any monitor(employee and fence lines)			
<b>Site Activities</b>	<ul style="list-style-type: none"> <li>Continuing to spray and pull material from the legacy to the piles</li> <li>Installed rig mats around working area</li> <li>Working pad is getting slick requiring mats and wood chips</li> </ul>			
<b>Odour Monitoring</b>	<b>Time</b>	<b>Odour Detection Level ( #/10)</b>		
		<b>On Pad</b>	<b>1 Mile</b>	<b>2 Mile</b>
	9:00	1	0	0
	10:00	0	0	0
	11:00	1	0	0
	12:00	1	0	0
	1:00	2	0	0
	2:00	0	0	0
	3:00	1	0	0
	4:00	0	0	0