

GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	April 14, 2020	Prepared By: Brad Walls		
	Temp (Celsius)	Wind Direction	Wind Speed (Km/Hr)	General Conditions
Meteorological Conditions	1-5 ^o C	NW	16	Light rain
	Removed (pH 2-14)	Processed (pH<2)		Removed
Legacy Volume (Mt)	144.768 Mt	0	Lime (Mt)	34.63 Mt
	Pile 9	Pile 10	Pile 11	
Composite pH	5.83	5.98	5.25	
H²S/ SO² Monitors	No Readings on any monitor (employee and fence lines)			
Site Activities	<ul style="list-style-type: none"> Continued moving legacy material into rows for testing and transport Loaded 5 trucks with legacy material and 1 truck with lime Continual spraying for odour. Operations shutdown at 12:30 -2:30 to load outgoing trucks 			
Odour Monitoring	Time	Odour Detection Level (#/10)		
		On Pad	1 Mile	2 Mile
	10:00 am	1	0	0
	11:00 am	1	0	0
	11:30 am	0	0	0
	12:30 pm	1	0	0
	1:00 pm	0	0	0
3:00 pm	1	0	0	

Note: Odour coming from Feedlot to the North and spreading manure on field to the South of the pond.