

GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	April 16, 2020	Prepared By: Brad Walls		
	Temp (Celsius)	Wind Direction	Wind Speed (Km/Hr)	General Conditions
Meteorological Conditions	-4 to 6 ^o C	SW	10	Sunny
	Removed (pH 2-14)	Processed (pH<2)	Lime (Mt)	Incoming Wood Chips (Mt)
Legacy Volume (Mt)	143.9 Mt	0	33.24 Mt	119.01 Mt
Composite pH	Pile 11	Pile 12	Pile 13	
	5.25	5.38	5.34	
H²S/ SO² Monitors	No Readings on any monitor (employee and fence lines)			
Site Activities	<ul style="list-style-type: none"> Laid down matting Continued moving legacy material into rows for testing and removal. Received 5 loads of wood chips Loaded 5 trucks with legacy material and 1 truck with lime Continuous spraying for odour. 			
Odour Monitoring	Time	Odour Detection Level (#/10)		
		On Pad	1 Mile	2 Mile
	10:00 am	1	0	0
	10:30 am	1	0	0
	12:00 am	1	0	0
	3:00 pm	1	0	0

Note: Odour coming from off-site manure spreading operation to the South.