

GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	April 17, 2020		Prepared By: Brad Walls	
	Temp (Celsius)	Wind Direction	Wind Speed (Km/Hr)	General Conditions
Meteorological Conditions	7 to 9° C	W N	19	Clear Morning
	Removed (pH 2-14)	Processed (pH<2)	Lime (Mt)	Incoming Wood Chips (Mt)
Legacy Volume (Mt)	116.50 Mt	0	34.89 Mt	103.88 Mt
Composite pH	Pile 13	Pile 14	Pile 15	
	5.34	6.88	6.89	
H²S/ SO² Monitors	No Readings on any monitor (employee and fence lines)			
Site Activities	<ul style="list-style-type: none"> Continued moving legacy material into rows for testing and removal. Received 4 loads of wood chips Excavating stopped at 11:55 am until 2:15 pm Loading started at 11:55 am to 2:15 pm of 4 trucks with legacy material and 1 truck with lime Site operations started again at 2:15 pm until 3:50 pm. Continuous spraying for odour. 			
Odour Monitoring	Time	Odour Detection Level (#/10)		
		On Pad	1 Mile	2 Mile
	9:30 am	0	0	0
	10:30 am	1	0	0
	11:00 am	1	0	0
	12:30 pm	1	0	0
	12:50 pm	1	0	0
	2:00 pm	1	0	0
	2:30 pm	2	0	0
	3:15 pm	1	0	0
3:30 pm	1	0	0	

Note: Received odour complaint (email) at 12:42 pm – conducted drive around at 12:50 pm at 1 mile and 2 mile radius from the site. Checked all employee and site H²S/ SO² Monitors.