GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	April 22, 2020		Prepared By: Brad Walls	
	Temp (Celsius)	Wind Direction	Wind Speed (Km/Hr)	General Conditions
Meteorological Conditions	8 to 12 ⁰ C	N	14	Overcast
	Removed (pH 2-14)	Processed (pH<2)	Lime (Mt)	Incoming Wood Chips (Mt)
Legacy Volume (Mt)	139.59 Mt	0	0	0
Composite pH	Pile 16	Pile 17	Pile 18	
	6.54	6.87	6.15	
H ² S/ SO ² Monitors	No Readings on any monitor (employee and fence lines)			
Site Activities	 Continued moving legacy material into rows for testing and removal. Loading of 5 trucks with legacy material Continuous spraying for odour. No lime was removed or wood chips received today. 			
Odour Monitoring	Time	Odour Detection Level (#/10)		
		On Pad	1 Mile	2 Mile
	9:00 am	1	0	0
	10:00 am	1	1	0
	11:00 am	1	1	0
	12:00 pm	0	0	0
	2:30 pm	0	0	0
	3:00 pm	1	0	0
	4:00 pm	0	0	0