

## GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

<b>Date:</b>	April 24, 2020	<b>Prepared By:</b> Brad Walls		
	<b>Temp (Celsius)</b>	<b>Wind Direction</b>	<b>Wind Speed (Km/Hr)</b>	<b>General Conditions</b>
<b>Meteorological Conditions</b>	6 <sup>o</sup> C	W	10	Overcast
	<b>Removed (pH 2-14)</b>	<b>Processed (pH&lt;2)</b>	<b>Lime (Mt)</b>	<b>Incoming Wood Chips (Mt)</b>
<b>Legacy Volume (Mt)</b>	142.79 Mt	0	32.79 Mt	0
	<b>Pile 19</b>	<b>Pile 20</b>	<b>Pile 21</b>	<b>Pile 22</b>
<b>Composite pH</b>	6.27	5.60	5.94	5.86
<b>H<sup>2</sup>S/ SO<sup>2</sup> Monitors</b>	No Readings on any monitor (employee and fence lines)			
<b>Site Activities</b>	<ul style="list-style-type: none"> <li>Continued moving legacy material into rows for testing and removal.</li> <li>Loading of 5 trucks with legacy material</li> <li>Loading of 1 truck of lime.</li> <li>Continuous spraying for odour.</li> <li>Repair of matting road</li> </ul>			
<b>Odour Monitoring</b>	<b>Time</b>	<b>Odour Detection Level ( #/10)</b>		
		<b>On Pad</b>	<b>1 Mile</b>	<b>2 Mile</b>
	10:00 am	1	0	0
	10:30 am	2	0	0
	11:00 pm	1	0	0
	12:00 pm	1	0	0