

GFL – STRATHMORE COMPOST FACILITY - DAILY REPORT

Date:	April 30, 2020		Prepared By: Brad Walls	
	Temp (Celsius)	Wind Direction	Wind Speed (Km/Hr)	General Conditions
Meteorological Conditions	9-20 ⁰ C	SW	14	Sunny
	Removed (pH 2-14)	Processed (pH<2)	Lime (Mt)	Incoming Wood Chips (Mt)
Legacy Volume (Mt)	130.92 Mt	0	36.92	14.62
	Pile 26	Pile 27	Pile	Pile
Composite pH	5.03	5.64		
H²S/ SO² Monitors	No Readings on any monitor (employee and fence lines)			
Site Activities	<ul style="list-style-type: none"> • Continued moving legacy material into rows for testing and removal. • Loading of 5 trucks with legacy material • Loaded 1 truck of lime • 2 loads of wood chips unloaded • Continuous spraying for odour. • On site – fence line debris clean up ongoing • Higher winds (40 km/hr) from the West most of the day 			
Odour Monitoring		Odour Detection Level (#/10)		
	Time	On Pad	1 Mile	2 Mile
	10:00 am	0	0	0
	11:00 am	0	0	0
	12:00 pm	1	0	0
	3:00 pm	1	0	0
	3:30 pm	2	0	0
4:00 pm	0	0	0	